

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
CAL
21-NOVA,
1BT-

HABS No. CA-2398-BT

Hamilton Field,
Double Non-Commissioned Officers' Quarters Type D
San Jose Drive and Crescent Drive
Novato
Marin County
California

David G. De Vries, photographer

(see note for dates)

Note: These facilities are similar or identical, and are grouped together for documentation purposes. Type NCO-D includes Facility Nos. 567, 568, 569, 570, 571, 572, 576, 578, 580, 582, 584, 586, 588, 590, 592, 594, 596, 598, and 599. Interiors were photographed on February 10, 1995. Front and side exteriors were photographed on November 23, 1994; the rear elevation was photographed on February 15, 1995.

Photograph No. CA-2398-BT-1 is a view of Facility No. 576, at 143/145 Crescent Drive.

CA-2398-BT-1 SOUTHWEST FRONT.

Photograph No. CA-2398-BT-2 is a view of Facility No. 578, at 151/153 Crescent Drive. The east side is a mirror image of this side.

CA-2398-BT-2 WEST SIDE.

Photograph No. CA-2398-BT-3 is a view of Facility No. 598, at 285/287 Crescent Drive.

CA-2398-BT-3 NORTH (REAR) ELEVATION.

Photographs Nos. CA-2398-BT-4 through CA-2398-BT-9 are views of Facility No. 588, at 231/233 Crescent Drive.

CA-2398-BT-4 LOOKING INTO DINING ROOM AND LIVING ROOM FROM KITCHEN DOORWAY.

CA-2398-BT-5 KITCHEN, IRONING BOARD CLOSET, DOOR TO BASEMENT.

Hamilton Field,
Double Non-Commissioned Officers' Quarters Type D
HABS No. CA-2398-BT
INDEX TO PHOTOGRAPHS

(page 2)

CA-2398-BT-6 LIVING ROOM TO DINING ROOM, WITH FOYER AT LEFT.
CA-2398-BT-7 FOYER AND STAIRS FROM LIVING ROOM.
CA-2398-BT-8 MASTER BEDROOM, WITH CHIMNEY AT HEAD OF BED.
CA-2398-BT-9 UPSTAIRS BATHROOM.